

██████████, Aquaculture Tech.

November 16, 2017

Interviewer: ██████████

Note Taker: ██████████

Cooke Aquaculture Lawyer: Diane Myers

July 2017 Incident:

- ██████████ has been with Cooke for 6 months.
- All Cooke boats were involved, also the Levrick.
- Deckhand on the Clam Digger with ██████████
- Arrived to relieve ██████████ holding the Site in place and checking anchors.
- Assisted running chains across the Site from one anchor to another across the pontoons.
- Some anchors are set from the boat that ██████████ works on.

August 2017 Incident:

- Got a text early in the am hours, ██████████ was on Site with the boat.
- ██████████ was holding the Site, a tug was onsite.
- Disassembled electrical panels and removed them.
- Worked assembling anchor systems.
- Salvage operations seemed like they took a month.
- Helped Global Diving with debris removal, mostly removing hand rails and old crab pots from the bottom.
- In August Site 2 was very close (a stones through away), from Site 1.
- Site 2 began to collapse close to where it was originally anchored.
- ██████████ boat handles sein nets during harvest operations.